

Bilddokumentation Befahrung

89567 Sontheim Grabenstraße
Von :10149 Nach :10150 Flr. :in




0:15:12
22.05.23 LZ1: 45.9m 8cm/s -0.2%

This video frame shows a tunnel with a large pipe in the center. Water is flowing through the pipe, creating a splash on the right side. The tunnel walls are made of concrete. A circular inset in the top right corner shows a location map with a green dot. The video player interface at the bottom shows a timestamp of 0:15:12, a date of 22.05.23, a length of LZ1: 45.9m, a speed of 8cm/s, and a slope of -0.2%.

89567 Sontheim Kanalgasse
Von :10269b Nach :10270 Flr. :in

Pos: 2; Oberflächenschaden, Bewehrung sichtbar, mechanische Beschädigung



0:09:27
22.05.23 LZ1: 32.7m 0cm/s -0.7%

This video frame shows a tunnel with a large pipe in the center. Water is flowing through the pipe, creating a splash on the right side. The tunnel walls are made of concrete. A circular inset in the top right corner shows a location map with a green dot. The video player interface at the bottom shows a timestamp of 0:09:27, a date of 22.05.23, a length of LZ1: 32.7m, a speed of 0cm/s, and a slope of -0.7%.


89567 Sontheim

Grabenstraße

Von :10270

Nach :10271

Flr. :in



0:00:48

22.05.23

LZ1: 1.2m



6cm/s

+1.2%



89567 Sontheim

Grabenstraße

Von :10271

Nach :10282b

Flr. :in



0:05:15

22.05.23

LZ1: 24.1m



18cm/s

-0.6%

89567 Sontheim

Grabenstraße

Von :10149

Nach :10150

Flr. :in



0:08:24

22.05.23

LZ1: 26.5m



8cm/s

-0.7%


89567 Sontheim

Grabenstraße

Von :10149

Nach :10150

Flr. :in



0:09:04

22.05.23

LZ1: 27.1m



0cm/s

0.0%